QUALITY CONTROL

BR No: 94 | 31-5-2013.

Name of the Work: Providing cement concrete roads at Jarakabande kaval stum 5th cross kammagondanahalli in ward no-12 Shettyhalli Sub-Division.

On verification of quality control test reports available in the file and also from inspection report of Technical Team Deployed for this purpose generally the work executed is satisfactory. Compliance of Quality Control Test Reports as per MORT&H at this stage is not feasible since this work was executed 9 years back.

Assistance Executive Engineer
Shetty Malli Sub Division
Bruhat Bengaluru Mahanagara Palike

19/6

Executive Engineer
Dasarahalli Division, Dasarahalli Zone
Bruhat Bengaluru Mahanagara Palike